



DAILY WORK ORDER

DATE: JULY 12 2021		TASK ORDER: 8-MANI		PAGE 1 OF 1				
WORK SITE NAME: MANILA LODGE		MONITOR(S)						
LOCATION (CITY, STATE): MONTEZUMA CO		SHIFT 1 2 3		START TIME: 0700 STOP TIME:				
CONTRACTOR: ENVIRONMENTAL RESTORATION LLC		OSC: PAUL PERONARD, MARTY MCCOMB		TO COMPLETION DATE TBD				
1. WORK AUTHORIZED		WORK ACCOMPLISHED						
1. Mobilize Crew and equipment		1. RM, FMN, 2 Ops and 1 Tech arrived and checked into local lodging. Dozer and loader delivered by vendors						
WEATHER CONDITIONS ENCOUNTERED:		GOOD						
2. NUMBER OF PERSONNEL AUTHORIZED								
1	RESPONSE MANAGER	0	TRUCK DRIVER	1	FOREMAN	2-3	OPERATORS	OTHER (SPECIFY)
1	CLEANUP TECH	1	ACCOUNTANT		H&S TECH.	0	LABORERS	
3. EQUIPMENT AND EXPENDABLE MATERIALS AUTHORIZED								
ITEM	QTY	USED	NOT USED / OR DOWN	ITEM	QTY	USED	NOT USED / OR DOWN	
Dozer	1	1		Compactor	1			
Water Trailer	1			Portable Toilets/handwash	3			
Front End Loader	1	1						
Pickup Trucks	3	3						
75Klb Exc	1							
Mini Exc	1							
4. AMENDMENTS (INCLUDE TIME)								
NONE								
SIGNATURE OF OSC			SIGNATURE OF RESPONSE MANAGER					
X _____			X _____					