

# Red and Bonita Mine Discharge Relocation Site

---

## Photo Log

---

Description: View of mine drainage into the iron fen

Category: Site Photo

Latitude:

Date Taken:

Longitude:

Tags:

---



Description: View of the adit with an abandoned well casing (to be removed).

Category: Site Photo

Latitude:

Date Taken:

Longitude:

Tags:

---



Description: Location of the earthen channel before it was created.

Category: Site Photo

Latitude:

Date Taken: 8/5/2023

Longitude:

Tags:

---



Description: View of the earthen channel circumventing the iron fen

Category: Site Photo

Latitude:

Date Taken: 8/5/2023

Longitude:

Tags:

---



Description: Image of the sump, flume, and earthen channel.

Category: Site Photo

Latitude:

Date Taken: 8/5/2023

Longitude:

Tags:

---



# Red and Bonita Mine Discharge Relocation Site

---

## Photo Log

---

Description: EPA Contractors installing a culvert under the road to allow drainage in the new location.

Category: Site Photo

Latitude:

Date Taken: 8/7/2023

Longitude:

Tags:



Description: View of the new culvert location covered and hidden in the road.

Category: Site Photo

Latitude:

Date Taken: 8/7/2023

Longitude:

Tags:



Description: View of the conveyance line entering the new culvert location with the flume in the background. The iron fence is to the right of this photo.

Category: Site Photo

Latitude:

Date Taken: 8/7/2023

Longitude:

Tags:



Description: Water exiting the conveyance line and entering the sump, flume, and earthen channel.

Category: Site Photo

Latitude:

Date Taken: 8/7/2023

Longitude:

Tags:



# Red and Bonita Mine Discharge Relocation Site

---

## Photo Log

---

Description: Image of the water leaving the new earthen channel and entering an existing channel where it will then enter Cement Creek.

Category: Site Photo

Latitude:

Date Taken: 8/7/2023

Longitude:

Tags:



Description: Close up image of the flume allowing water height measurements.

Category: Site Photo

Latitude:

Date Taken: 8/5/2023

Longitude:

Tags:



Description: Image of conveyance line welding.

Category: Site Photo

Latitude:

Date Taken: 8/7/2023

Longitude:

Tags:



Description: View of EPA contractors welding the "T" in the conveyance line.

Category: Site Photo

Latitude:

Date Taken: 8/7/2023

Longitude:

Tags:



# Red and Bonita Mine Discharge Relocation Site

---

## Photo Log

---

Description: View of the new "T" location in the conveyance line. The conveyance line takes MIW from the mine adit to the culvert and earthen channel.

Category: Site Photo

Latitude:

Date Taken: 8/7/2023

Longitude:

Tags:

